BOARD OF COUNTY COMMISSIONERS' (BOCC) CONCURRENCE FORM



This form must be completed for all staff reports being prepared for BOCC meetings/public hearings and is the cover sheet for the staff report. The original (single-sided) staff report needs to be submitted to the County Manager's Office one (1) week in advance of the scheduled presentation date. For Closed Sessions please submit the original (single-sided) and 8 (double-sided copies) of the staff report.

To: Office of the County Manager
From (Name & Division): Regina Howell, Budget Officer, County Mgr. Phone #: x13191
Requested Meeting Date (mm/dd/yr): 01/24/13 Est. Presentation Time: 5 minutes
Staff Report Topic: (The text provided here will also be reflected on the meeting agenda and county's website.)
County Budget Transfer - BT-13-107 Division of Fire & Rescue
County Funds Requested/Required: \$_0-
Type of Meeting:
(Click to place a check mark in the following appropriate boxes.)
Administrative Business (The Consent Agenda Committee determines which items are eligible for the consent agenda.
Worksession Closed Session Public Hearing (a.m. or p.m.)
BOCC/BOE Mtg. County/Municipalities Mtg.
Power Point Presentation
Board Action Desired: 🗸 Decision 🗌 Guidance 📗 Information
Staff Report Review:
This staff report has been thoroughly reviewed first by the appropriate divisions/agencies noted on <u>Page 2</u> followed by those outlined below :
Initials Date Comments Y/N (Page 2)
✓Budget Officer
✓Finance Director JID WEN 1/1/13
County Attorney's Office
County Manager

Other Reviewing Divisions/Agencies: (Click to place a check mark in the following appropriate spaces.) Comments Y/N (noted below) <u>Initials</u> <u>Date</u> __ Animal Control Business Development & Retention __ Citizens Services Community Development Emergency Management Fire & Rescue Services __ Health Services __ Human Resources __ Interagency Information Technologies __ Internal Audit _ Parks & Recreation _ Public Works _ Transit Services __ Utilities & Solid Waste Management _Other: ______ __Other: _____ _Other: ____ **Elected Officials or Independent Agencies:** Comments Y/N (noted below) Initials <u>Date</u> Board of Education __ Board of Elections Board of License Commissioners ___Citizens Care & Rehabilitation Center/ Montevue Assisted Living Frederick Community College Frederick County Public Libraries Sheriff's Office __ Social Services State's Attorney's Office Comments: Date: 1. <u>From:</u> Date: 2. From: Date: 3. From: 4. From: Date:

Date:

5. <u>From:</u>



FREDERICK COUNTY GOVERNMENT OFFICE OF THE COUNTY MANAGER

Budget Office Regina M. Howell, CPA, Budget Officer

12 East Church Street Frederick, Maryland 21701

www.FrederickCountyMD.gov

O: 301-600-3191 F: 301-600-2305

Commissioners

Blaine R. Young President

C. Paul Smith Vice President

Billy Shreve David P. Gray Kirby Delauter

Lori L. Depies, CPA County Manager

EXECUTIVE SUMMARY

Staff Report Topic: County Budget Transfer #13-107

County Funds Requested/Required: \$ -0-

County Budget Transfer #13-107 – Submitted by the Division of Fire & Rescue to transfer \$21,728 from the Returned Money Fund to vehicle repairs for Walkersville Volunteer Fire Department.

Staff recommends approval of County Budget Transfer #13-107.

GE1_	of1			
	· —	FREDERICK COUNTY BUDGET TRANSFER		
January	14 2013	TRANSFER NO.:	BT- 13	101-6
Request		_		5-107
Division	of Fire Rescue	Steve Leatherman	Tom Owens	149
Departn		Department Head	Tom Owens / Division Direct	of 1/MUS
DESCO	IDDIAN/DE LOAN EAD DEATH	eow.	ı	/
DESCR	IPTION/REASON FOR REQUI	E91:		
of the W estimate account	/alkersville VFD has suffered a c	Ioney Fund to the vehicle repair account under Dept. catastrophic engine failure requiring extensive repairs move funds from the Return Money Account to the vikersville VFD.	. The total	
VENUE:				
New #	Fund-Dept-Project-Acct #	Account Description	Increase	Decrease
	10-8211-45924-F00015	Misc Revenue	21,728	
		COLV	21.720	0
		Net Change TOTAL	21,728	U
	RES: APPROPRIATIONS (PEO Fund-Dept-Project-Approp	OPLESOFT)- PERSNL, OPERAT, CAPITA, and RE Appropriation Description	ImB Increase	Decrease
	10-8211-F00015-OPERAT	Operating Approp	21,728	
		TOTAL	21,728	
ENDITU	RES: ACCOUNT LINE DETAI	Net Change IL	21,728	
New#	Fund-Dept-Project-Acct #	Account Description	Increase	Decrease
	10-8211-F00015-52463	Vehicle Repairs	21,728	
		10 100		
		A second of the		
		The state of the s		
	. •	Ny. Course		
		€ _K , ♦ _K		

PRESIDENT, BOCC DATE APPROVED

TOTAL

21,728 21,728

Net Change

Leatherman, Steve (FCFRS)

From:

Staley, Matthew

Sent: To: Friday, January 11, 2013 7:24 AM Leatherman, Steve (FCFRS)

Subject:

FW: Estimate 41617, Quint 11

Attachments:

User Cubbage.vcf; Seagate Crystal Reports - est1.rpt_15.pdf

Hi Steve,

Attached is the estimate cost to repair the engine on Q-11 from EVS of Hagerstown, that you requested. As you will see the cost is \$19,449.59.00, which may go up \$1643.60 if there is no core credit available for the cylinder head, as it is damaged beyond repair. I just received this last night and wanted to get it to you as soon as possible, to see if there is any emergency repair money available. Because of the dollar amount, I want to make sure we are following the proper county purchasing procedures for emergency repairs. I also spoke to Vaughn Zimmerman last night and gave him the same information.

I also received the bill from Marks Equipment and Repair in the sum of \$634.00, to tow Q-11 to Hagerstown. Since this is all related, can this be added to the to the above amount if money is available?

The repairs will take approximately 2 to 3 weeks depending on parts delivery. Please let me know if you need any other information, or have any questions.

Thanks,

Matt Staley Chief WVFC Cell (301)-418-2592

From: Emergency Vehicle Specialist [mailto:Kimble.Trucking@myactv.net]

Sent: Thursday, January 10, 2013 4:31 PM

To: Staley, Matthew

Subject: Estimate 41617, Quint 11

Emergency Vehicle Specialist

16121 Business Parkway Hagerstown, MD. 21740-4201 Phone - 301-739-7973 Fax - 301-739-7975 Sub Estimate For Order # 041617

Estimate Date: 01/10/2013

Odometer In: 0

Federal ID #20-2518148

Visit us on the Web at: www.EVSpecialist.com

ESTIMATE FOR SERVICES

Walkersville Vol. Fire Co. 11

Staley, Matt P.O. Box 425

Walkersville, MD 21793 Cellular 301-418-2592

Cust Id: 914

2000 Pierce - Lance # 11278

Lic#: T-Q11-K

Unit #: Quint 11

VIN #: 4PICT0250YA000565932

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended	
15W/40 Mobil 1 Motor Oil				1. Check engine for possible injector problem.	1,929.00	
15/	40.00	5.59	223.60	Vehicle was towed in to our facility.		
Antifreeze Coolant				Connected computer to check for codes and gain		
AF2	12.00	13.59	163.08	data. Data showed #4 injector faulty (12		
Serp blt				occurrences). Drained coolant, and removed upper		
25-080510	1.00	51.71	51.71	radiator hose. Removed valve cover. Removed rear		
Injector				Jake brake housing, rocker arms on rear half of		
DDE/R5237650	6.00	528.08	3,168.48	engine to access injector. Removed #4 injector.		
Screw Asm Exhaust				Replaced injector with reman and set lash.		
DDE/23537089	2.00	12.79	25.58	Removed front Jake housing and adjusted all		
Hose Assembly				valves. Removed alternator and tightened fan		
P2010879-6-6-6-28	1.00	98.91	98.91	guard on back. Reinstalled alternator. Removed		
Oil filter				and replaced supply fuel line on right side of		
1971	2.00	30.03	60.06	engine and replaced with new. Reassembled all		
Fuel filter				components listed and filled with coolant. Started		
3118	1.00	14.98	14.98	engine. Engine runs very rough and smokes badly.		
Fuel filter				Checked exhaust manifold with heat gun and found		
3120	1.00	15.60	15.60	number 5 cylinder not building heat. Removed 3rd		
TURBO				valve cover and pulled Jakes. Removed number 5		
DDE/E23534004	1.00	2,795.09	2,795.09	injector and found tip of injector missing.		
TURBO CORE		,	•	Performed pressure test on cylinder number 5 and		
TURBO CORE	1.00	500.00	500.00	found pressure bleeding over into intake. Test		
TURBO CORE				suggests one or more intake and exhaust valves are		
TURBO CORE	-1.00	500.00	-500.00	damaged. We also noted the air system is		
GASKET				contaminated with oil and diesel fuel. Removed all		
DDE/08929529	1.00	7.36	7.36	necessary components to remove cylinder head.		
M-NUT				Removed head and found the number 5 intake		
DDE/11506101	4.00	1.90	7.60	valve head is missing and other valves are bent.		
M-GASKET				Damage to the top of piston and valve seat		
DDE/08959285	1.00	6.80	6.80	damaged beyond repair.		
M-STUD EX				2. Estimate to complete repairs.	3,858.00	
DDE/23507438	4.00	13.29	53.16	Remove oil pan, replace number 5 piston, liner,		
CYLINDER HEAD				and connecting rod. Install remanufactured		
DDE/R23525566	1.00	2,585.39	2,585.39	cylinder head, 6 new injectors. We recommend		
CYLINDER HEAD CORE		-	•	replacing turbo, thermostats, and fan belts. Clean		
CYLINDER HEAD CORE	1.00	1,643.60	1,643.60	intake and exhaust manifolds. Reassemble engine		
M-HD GASKET		•	•	using listed parts. Torque head and Jake		
DDE/23532333	1.00	289.94	289.94	assemblies and adjust valves to manufacturer's		
BOLT P			-	specifications. Clean and decontaminate air		
Kimble, Jimmy			Page	l = -	est17.01.04	
renewal country			30	• • •		

Emergency Vehicle Specialist

16121 Business Parkway Hagerstown, MD. 21740-4201 Phone - 301-739-7973 Fax - 301-739-7975

કેદ	ıb Estimate For Order	#
	041617	

Estimate Date: 01/10/2013

Odometer In: 0

Federal ID #20-2518148

Visit us on the Web at: www.EVSpecialist.com

ESTIMATE FOR SERVICES

Walkersville Vol. Fire Co. 11

Staley, Matt P.O. Box 425

Walkersville, MD 21793 Cellular 301-418-2592

Cust Id: 914

2000 Pierce - Lance # 11278

Lic#: T-Q11-K

Unit #: Quint 11

VIN #: 4PICT0250YA000565932

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
DDE/23530768	38.00	13.23	502.74	system. Install new air dryer and cartridge. Change	
CYLINDER K				oil, oil filter and fuel filters.	
DDE/R23532554	1.00	865.05	865.05		
M-SHELL K					
DDE/23526142	1.00	83.12	83.12		
Thermostat					
DDE/23532436	2.00	91.25	182.50		
GASKET					
DDE/23539104	1.00	138.42	138.42	,	
CAMSBRG SE					
DDE/08929690	7.00	38.90	272.30		
Fuel Injector Wiring Harness					
23526101	1.00	257.52	257.52		
Misc hardware & materials					
Misc	1.00	150.00	150.00		

Parts: \$ 13,662.59 Total: \$ 19,449.59 Labor: \$ 5,787.00

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. SMOG: I understand that I can have emission service and/or adjustments done elsewhere. I hereby waive this right.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ____days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

SIGNATURE	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Date	Time	
Kimble, Jimmy	Page 2 of 2			est17.01.04

Mark's Equipment Service, Inc. 5090 Mountville RD Frederick, MD 21703 - 7858

Invoice

DATE	INVOICE #	
1/7/2013	51690	

BILL TO	
Walkersville Vol. Fire Co. 79 W. Frederick St. Walkersville, Md. 21793	

•	P.O.	NO.	TERMS
	Quir	nt 11	Due on receipt
DESCRIPTION	QTY	RATE	AMOUNT
Towing charge ticket #38423	1	634.00	634.00
Thank You For Your Business !!!!!! We accept credit cards for your payments. Finance charges of 1.5% per month will be applied to amounts 30 days or more overdue with a \$5.00 minimum billing charge.			0.00
MD Sales Tax		6.00%	0.0
`			
·			
<u> </u>			
		Total	\$634.00

Leatherman, Steve (FCFRS)

From:

Staley, Matthew

Sent:

Friday, January 11, 2013 7:36 AM Leatherman, Steve (FCFRS)

To: Subject:

Attachments:

FW: IMG-20130109-00351.jpg

Hi Steve, Here is one picture from Q-11, as you can see the piston is mashed down in the middle from the valve beating on it, not good. I will send you a second one soon. Sorry I couldn't get them both in the same e-mail.

Matt



Leatherman, Steve (FCFRS)

From:

Staley, Matthew

Sent: To:

Friday, January 11, 2013 7:38 AM Leatherman, Steve (FCFRS)

Subject:

FW:

Attachments:

IMG-20130109-00345.jpg

Hi Steve, Second picture shows the missing valve and the bent second valve. Also the hole in middle is where the injector was sticking out.

Matt

